COUNTRY Po	Approved For Release 2001/03/06. CIA-RDP82-00 security information REPO	1457RU RT NO.	54
	row-Okecie Airfield	25X	1A
,		25X1C	
EVALUATION	F - 5 PLACE OBTAINED	American desta 1 miles (1984 - 1986 -	Alleganisms observator kapinar vibrar at ung kapaton.
DATE OF CON	25¥1C		
DATE OBTAIN		7 December 1951	alangunings compressed polymera to state to be obtained to
REFERENCES	05V4 A	-cyclesia-	Company of the Act of the Company of
, , , , , , , , , , , , , , , , , , , ,	1ENCLOSURES (No. & TYPE)	to alleg providen	
REMARKS		April 2 Auditor	
The Private Community	WW.		
	RETURNARY		
gyjeginnenydy, _P o Yffelden met von metholishede is e deem	The same second		
SOURCE	25X1X	OR CONTINUED AND GOOD PLANTING THE PROPERTY OF	Name and the Control of the Control
	No construction was observed at Warsaw-Okecie (R and August 1951. Only one concrete ruray could be field. Six brick hengars with rounded roofs we tion of the field. Some of the hangars which had were repaired and others were reconstructed. Six located along Grojeck road in the northwestern se occupied by air force soldiers. An entrance to section was guarded by air force sentries. Some billeting area. Some trucks were parked near the large white L painted on both sides of their super In the eastern section of the field there was a him which several hundred fuel containers were stocked at the several hundred fuel containers were stocked at the parked. A spur track led up to the hangar.	se identified on the land or the in the northern social been damaged during the four-story brick build ection of the field were the field in the northwe garages were observed in the sector of the trucks pretructures. Inangar, about 100 x 150 mored. The hangar had an	over inge fully extern in the had a
25X1X 3。	there was an aircraft plant with laboratories in which experimental work was dome. Engine test stands existed in the factory area. The chief am section chiefs of the factory were allegedly Soziets.		
4.	Three single-engine aircraft and three twin-engine planes with radial engines, single rudder assemblies, and cabin windows were observed at the field. *		
25X1A *	Comment. The report confirms the progress made in reconditioning work at Mersaw-Okecie airfield, particularly with regard to the hangars and billets. dowever, it is believed that the field has at least two, possibly, three runways. It is also believed that the field is mainly used by civilian planes and that it is possibly still occupied by an air transport unit. The aircraft plant is the former German Air Force Aeronautical Test Station.		
			•
IO/B	CLASSIFICATION TO THE OFFICE	ALS OULY	Managara wang per wang panagaran pengangan dibahkan
•	· · · · · · · · · · · · · · · · · · ·	Document No. 905	
	DEFENSE CODY	No Change in Comment	